

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	1263 telescop\$3 near5 plunger\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/29 16:44			0
2	BRS	L2	130 L1 and (plunger near10 thread\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/29 16:46			0
3	BRS	L3	64 L2 and (rotat\$5 same plunger)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/29 16:46			0

Type	#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	Errors
1	BRS	L1	1263 telescop\$3 plunger\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/29 16:44			0
2	BRS	L2	130 L1 and near10 (plunger near10 threads\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/29 16:46			0
3	BRS	L3	64 L2 and (rotat\$5 same plunger)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/29 16:46			0